
Application: B.A. threads are used for fine fastening, especially in instruments.



MANUFACTURING RANGE

B.A. No	Pitch in mm	Type of Thread Gauges used			
2	0.81	Thread Plug Gauges	Thread Ring Gauges	Check Plug Gauges	Wear Check Plug Gauges
3	0.73			to check NEW Ring	to check/ calibrate used
4	0.66			Gauges.	Ring Gauges.
5	0.59	Tolerance class :	Tolerance class :	Tolerance class :	Tolerance class :
6	0.53	Normal (N)	 Normal (N) 	Normal (N)	Normal (N)
7	0.48	Close (C)	• Close (C)	• Close (C)	• Close (C)







